

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
1594 West North Temple - Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801  
Telephone: (801)538-5291  
Fax: (801) 359-3940

RECEIVED  
JAN 31 2005  
DIV. OF OIL, GAS & MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/2004 To (mo./yr.) 12/2004
  2. DOGM File Number (Mine No.): S/550/016
  3. Mine Name: Torrey Quarry
  4. Mineral(s) Mined (or permitted to mine): Sandstone
  5. Type of mine: ☒ Surface Mine or ☐ Underground Mine
  6. Legal Description (Location of Lands Affected):  
SE 1/4, 1/4, 1/4, Section 8, Township 29S, Range 5E  
1/4, 1/4, 1/4, Section , Township , Range  
1/4, 1/4, 1/4, Section , Township , Range
  7. Name of Operator or Company: Star Stone Quarries, Inc.
  8. Permanent Street Address: 4040 South 300 West  
City, State, Zip: Salt Lake City, Utah 84107  
Phone: 801-262-4300 Fax: 801-262-5069
  9. Company Representative (or designated operator):  
Name: Lon Thomas  
Title: President  
Business Address: Same as above  
City, State, Zip: \_\_\_\_\_  
Phone: \_\_\_\_\_ Fax: \_\_\_\_\_
- ☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☐ No ☒
2. If no - what was the last year of activity? 2002
3. If yes - how much ore or mineral was mined? \_\_\_\_\_

Reviewed 2/2/05  
PMB Acreage discrepancy noted.



4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.

none

5. How much **additional acreage** was disturbed during the past year? 0

6. How much acreage was **reclaimed** during the past year? 0

7. Briefly describe the reclamation work performed during the past year. This description should include methods employed and an evaluation of the results.

none

8. What is the **total disturbed acreage of entire project** at years end? 5

9. Briefly summarize any mining and/or reclamation plans for the upcoming year.

Resume quarry bench operation

**NOTE:** Section III., "Additional Information" applies only to **large mining operations**.

III. *Additional Information - R647-4-121.2 and .3*

1. **The operator shall include an updated map depicting surface disturbance and reclamation performed during the year**, prepared in accordance with Rule R647-4-105.
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

IV. Signature Requirement

**I hereby certify that the foregoing is true and correct.**


Name (Typed or Print): Lon Thomas

Title of Operator: President

Signature of Operator: Lon Thomas

Date: 1-24-05





## TORREY QUARRY (S/550/016)

### STAR STONE QUARRIES, INC.

Surface Facilities/Development

2004 Disturbance  
and Reclamation Areas

1" = 264'